§ 35.400

\$35.390(b)(1)(ii)(G)(3) and/or 35.390(b)(1)(ii)(G)(4).

[70 FR 16365, Mar. 30, 2005, as amended at 71 FR 15010, Mar. 27, 2006]

Subpart F—Manual Brachytherapy

§35.400 Use of sources for manual brachytherapy.

- A licensee shall use only brachytherapy sources for therapeutic medical uses:
- (a) As approved in the Sealed Source and Device Registry; or
- (b) In research in accordance with an active Investigational Device Exemption (IDE) application accepted by the FDA provided the requirements of §35.49(a) are met.

§ 35.404 Surveys after source implant and removal.

- (a) Immediately after implanting sources in a patient or a human research subject, the licensee shall make a survey to locate and account for all sources that have not been implanted.
- (b) Immediately after removing the last temporary implant source from a patient or a human research subject, the licensee shall make a survey of the patient or the human research subject with a radiation detection survey instrument to confirm that all sources have been removed.
- (c) A licensee shall retain a record of the surveys required by paragraphs (a) and (b) of this section in accordance with §35.2404.

§ 35.406 Brachytherapy sources accountability.

- (a) A licensee shall maintain accountability at all times for all brachytherapy sources in storage or use.
- (b) As soon as possible after removing sources from a patient or a human research subject, a licensee shall return brachytherapy sources to a secure storage area.
- (c) A licensee shall maintain a record of the brachytherapy source accountability in accordance with §35.2406.

§35.410 Safety instruction.

In addition to the requirements of §19.12 of this chapter,

- (a) The licensee shall provide radiation safety instruction, initially and at least annually, to personnel caring for patients or human research subjects who are receiving brachytherapy and cannot be released under §35.75. To satisfy this requirement, the instruction must be commensurate with the duties of the personnel and include the—
- (1) Size and appearance of the brachytherapy sources;
- (2) Safe handling and shielding instructions:
- (3) Patient or human research subject control;
 - (4) Visitor control, including both:
- (i) Routine visitation of hospitalized individuals in accordance with §20.1301(a)(1) of this chapter; and
- (ii) Visitation authorized in accordance with $\S 20.1301(c)$ of this chapter; and
- (5) Notification of the Radiation Safety Officer, or his or her designee, and an authorized user if the patient or the human research subject has a medical emergency or dies.
- (b) A licensee shall retain a record of individuals receiving instruction in accordance with §35.2310.

§35.415 Safety precautions.

- (a) For each patient or human research subject who is receiving brachytherapy and cannot be released under §35.75, a licensee shall—
- (1) Not quarter the patient or the human research subject in the same room as an individual who is not receiving brachytherapy;
- (2) Visibly post the patient's or human research subject's room with a "Radioactive Materials" sign; and
- (3) Note on the door or in the patient's or human research subject's chart where and how long visitors may stay in the patient's or human research subject's room.
- (b) A licensee shall have applicable emergency response equipment available near each treatment room to respond to a source—
- (1) Dislodged from the patient; and
- (2) Lodged within the patient following removal of the source applicators.